## - Site Service Report -

Date:June 9, 2009

IRD SO.: 10407 IRD Contract No.:

From: Tim Weber To: ESS

State: Wisconsin

Project Name/Location: Hwy 29 Wausau WB

Service Date(s): November 12, 2008

Job Description: Semi-annual site inspection and install heat strips..

## **Work Completed:**

I stopped on site and did a visual inspection of the plates. They looked good.

I tested the loops and bending plates and recorded all of the results. I also megged out the loops and they looked good.

I measured the power and phone and recorded the results.

Before I left I had Ray Castros dial up the site to make sure he could connect to it. He said that he was able to.

The battery was at 5 VDC. The battery charger is not working properly. We will need to either install a new charger or new battery or both.

It was raining so they were not able to set up the lane closure. We will have to wait for warmer weather before we install the heat strips.

Work Remaining: Install heat strips, and change battery.

Parts Used: None

Mileage: 700 miles.

Hours Worked: 10 hours driving, 1 hour onsite. Total 11 hours.

## Notes:

## **Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		

6/19/96 IRD FORM No.: 1304A